

BAADER MACHINE

Illustrative safety sheet | Mini risk assessment

DEMO ONLY - NOT FOR OPERATIONAL USE

Fictional content. Replace with an approved, machine-specific SOP.



AI-generated illustrations: generic equipment and isolation hardware.

01 MAIN HAZARDS & EXAMPLE CONTROLS

Moving parts / entanglement

Contact with rollers or mechanisms can cause serious injury. Keep guards in place; keep hands, clothing and hair clear.

Unexpected start / stored energy

Before cleaning, clearing jams or maintenance, follow the approved isolation procedure; lock out and verify a safe energy state.

Sharp edges / cutting components

Cuts may occur during handling or servicing. Use approved tools and task-specific protection under the vessel procedure.

Wet decks / vessel movement

Slips and loss of balance can bring people into machinery. Keep access clear, manage spills and follow vessel operating limits.

02 BEFORE STARTING

Confirm training and authorisation. Review the approved SOP, pre-start checks, required PPE and emergency arrangements with the responsible supervisor.

FAULT OR UNSAFE CONDITION?

Stop work, keep clear and notify the responsible vessel supervisor.